

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO.

LOCATION

6411

1222-4<sup>TH</sup> ST.

PURPOSE

PHONES

DATE  
June 12  
1930

OWNER

Make General Repairs to South Brick Wall of Bldg.

MAX MARKOWITZ

ARCH'T

ZONE  
General  
Commercial

CONT'R

OWNER

VAL.

500<sup>00</sup>

STORIES

2

ROOMS

APTS.

SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

