

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. <i>A-503.</i>	LOCATION <i>3977 - L Street</i>	PURPOSE <i>Repair + Remod. front of Em. Ho. &amp; Hotel</i>		PHONES
DATE <i>Apr. 10. 33</i>	OWNER <i>E. E. Hyatt</i>	ARCH'T <i>Owner</i>		
ZONE <i>Gen. Com.</i>	CONT-R			
VAL. <i>500 00</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK-REMARKS
3/10/33	<p>Inspected Repairs to front steps and platforms          All window sills removed and new casings          sills and trim installed.          Casings half of front porch removed. ok          McLaughlin.          I'll check on same again next Friday.</p>
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>