

R293 F341

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$10.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>					
G-9741		<b>LOCATION</b> 5721 - 19th Avenue A-4 )30)			
<b>DATE</b>		PURPOSE Repair fire damage to dwelling			
Jan. 4-71		<b>OWNER</b> John Montgomery			
<b>ZONE</b>		<b>ARCH'T</b> 483-9246			
		<b>CONT'R</b> Building Improvement Co. 2530 - Telsa			
<b>VAL. \$800.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b> /Way	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	1-11-71	M Calloway			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b>

**INSPECTOR**