

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5625.</i>	LOCATION <i>5218 - 38th Street</i>			
DATE <i>7/18/37</i>	PURPOSE <i>Erect new dwlg & garage</i>			
ZONE	OWNER <i>Miller & Harrigan</i>			
	ARCH'T.			
	CONT'R <i>Miller & Harrigan</i>			
VAL. <i>4500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>1</i>	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 1300⁰⁰</i>
VENT SHAFTS		BOILER ROOMS	<i>@ 3,500⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
2/16/37	1st Insp	Frames on Printer
7/27/37	2 "	Frame on Printer
10/18/37	3 "	Lack a Printer
	COMPLETE AND O. K.	INSPECTOR

