


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8862</i>	LOCATION <i>1307-16th St</i>			
DATE <i>8/13/81</i>	PURPOSE <i>Make Int. Alterations & Rep' to Dwg's</i>			
ZONE <i>LM-RITHL</i>	OWNER <i>DR. A. H. HENDERSON, 1600 CAPITOL AVE</i>			
	ARCH'T.			
	CON'T'R <i>OWNER (day-work)</i>			
VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
8/29-41	2 nd Ins p frame OK 
	COMPLETE AND O. K. INSPECTOR