

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00

TYPE BUILDINGS *R 264 F 227*

PERMIT NO. <i>G-4214</i>	LOCATION <i>180 - San Antonio Way A-1 (3)</i>		
DATE <i>July-24-69</i>	PURPOSE <i>Repair pest damage to dwelling</i>		
ZONE <i>R-1</i>	OWNER <i>Gary Boyd 180 - San Antonio Wy</i>		
	ARCH'T		
	CONTR <i>Midstate Termite Co. 3300 - 47th Ave.</i>		
VAL. <i>\$300.</i>	STORIES	ROOMS	APTS. SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP PHONE (O) (C)
FORM	<i>7-4-69</i>	<i>Barbata</i>	
JOIST			
FRAME			
SHEET ROCK			
FINAL	<i>8-11-69</i>	<i>Barbata</i>	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
<i>P. 7.12.49</i>	<i>At Not Home</i> <span style="float: right;"><i>R. Jones</i></span>
COMPLETE AND OK	INSPECTOR