

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11084</i>	LOCATION <i>1631-53rd St.</i>
DATE <i>2/19/43</i>	PURPOSE <i>Re-build gar. & repairs to dwlg.</i>
ZONE	OWNER <i>Tom Angello</i>
	ARCH'T.
	CONTR. <i>Tom Angello</i>

VAL. <i>4500</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/22/43	2 ND VOSP. Frame for Repair to old duty. ^{or} HW Campbell
3/24/43	3 RD VOSP. E-7 LOCK 147 LOCK (PASCALING) ^{or} HW Campbell
	<p data-bbox="294 1009 446 1056">COMPLETE AND O. K.</p> <p data-bbox="1280 1032 1437 1056">INSPECTOR</p>