

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | |
|------------------------------|-------------------------|---------------------------------|-------|
| PERMIT NO. B-12427 | | LOCATION 3817. S. ST | |
| DATE 7/18/44 | | PURPOSE Enclose Porch | |
| ZONE 2-Fam. | | OWNER ROY YOUNG. | |
| | | ARCH'T. | |
| | | CONT'R. ROBERT HILL | |
| VAL. | 125⁰⁰ | STORIES | ROOMS |
| | | | APTS. |
| | | | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|------|---------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

COMPLETE
AND O. K.

INSPECTOR