


R 264 F 230

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00

TYPE BUILDINGS

| | | | |
|------------|--|---|--|
| PERMIT NO. | G-4217 | | |
| LOCATION | 3332 - 21st Avenue A-3 (37) | | |
| DATE | PURPOSE | July-24-69 Repair pest damage to dwelling | |
| OWNER | Columbus-Founders P.O. Box 90 Woodland | | |
| ZONE | ARCH'T | R-1 422-8880 | |
| | CONT'R | Midstate Termite Co. 3300 - 47th Ave. | |

| | | | | |
|-------------|---------|-------|-------|------|
| VAL. \$400. | STORIES | ROOMS | APTS. | SIZE |
|-------------|---------|-------|-------|------|

| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|-------|---------|---|-----------------|---------------|
| FORM | 8-8-69 | 2000 | | |
| JOIST | | | | |
| FRAME | | | | |
| SHEET | | | | |
| MOCK | | | | |
| FINAL | 8-24-69 |  | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|----------|---|
| 8-7-109 | <div style="display: flex; justify-content: space-between;"> 1st test steady Callaway </div> |
| 8-23-109 | <div style="display: flex; justify-content: space-between;"> 2nd test steady Rich </div> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div> |