


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>5243</b>	LOCATION <b>416 Dawson Place - 1250 - 1 Ward</b>		
	PURPOSE <b>Bull Res - Garage</b>	ROOMS <b>1</b>	APTS. <b>1</b>
DATE <b>10/1/29</b>	OWNER <b>Bentley Mechanical Co.</b>		PHONE <b>0</b>
ZONE	ARCH'T <b>Wood - Ford</b>		
	CONT'R <b>Wood - Ford</b>		
VAL. <b>3000</b>	STORIES <b>1</b>	SIZE <b>24 x 30 - 18</b>	

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
1	1 Insp Forms in place & ok
11/7/29	2 Insp Frame " " " " P H Rutter
11/8/29	3 Insp. Int Lath ok P H Rutter
11/11/30	4 Insp Finished & ok Certificate of
	Occupancy issued work of
	Street cleaned up.
COMPLETED AND O.K.	<div style="text-align: center;">  </div>
	INSPECTOR