

*9117 271*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> E-3313		<b>LOCATION</b> 4118 - 54th Street				<b>A-1</b>	
<b>DATE</b> Feb. 27-63		<b>PURPOSE</b> Const. patio cover in rear yard.					
<b>ZONE</b> R-1		<b>OWNER</b> Ernest & Nancy Olson				<b>Same</b>	
		<b>ARCH'T</b>					
		<b>CONT'R</b> Owner		<b>GL 6-1490</b>			
<b>VAL.</b> \$300.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b> 192 sq. ft.		
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>		
<b>FORM</b>							
<b>JOIST</b>							
<b>FRAME</b>							
<b>SHEET ROCK</b>							
<b>FINAL</b>	<i>7-8-63</i>	<i>C. Hammond</i>					

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b> <span style="float: right;"><b>INSPECTOR</b></span>