

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-11333	LOCATION 1501 - 3 St.
DATE 6/14/43	PURPOSE Repairs to front porch dry rot.
ZONE	OWNER A. Luddy
	ARCH'T.
	CONTR. Markwart Co.

VAL. 375⁰⁰	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS ✓		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K. INSPECTOR