

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-966</i>	LOCATION <i>2740 - 9th Ave -</i>
DATE <i>9/20/33</i>	PURPOSE <i>To Re Roof with cedar shingles.</i>
ZONE <i>F</i>	OWNER <i>Julu. Fred Lachenmeyer</i>
	ARCH'T <i>Owner</i>
	CONT-R

VAL. <i>5700⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
-------------------------------	------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
9/21/33	Made Partial Inspection of Re Shingling of Roof with Cedar Shingles. A.W. Campbell
	COMPLETE AND O. K. INSPECTOR