

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8601</i>	LOCATION <i>1525-39th St.</i>
DATE <i>9/18/31</i>	PURPOSE <i>Gen. Rep. Patch</i>
ZONE <i>Wm</i>	OWNER <i>Frank Atkinson</i>
	ARCH'T <i>W R Saunders</i>
	CONT-R <i>W R Saunders</i>

VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/22/31	1 ST /NSP (PARTIAL) Repairs to Front Porch w. Dry Rot. O.K. A.W. Campbell
9/29/31	2 ND /NSP. Frame for New Stucco Columns A.W. Campbell
9/29/31	3 RD /NSP. EXT. LATH FOR " " " " " " A.W. Campbell
	COMPLETE AND O.K. INSPECTOR