

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,790</i> DATE <i>10/19/42</i> ZONE	LOCATION	<i>3320 - 7th</i>
	PURPOSE	<i>Erect new dwg. on</i>
	OWNER	<i>Tom Brazil</i>
	ARCH'T.	
	CONTR.	<i>Owner</i>

VAL.	<i>3400</i>	STORIES	<i>1</i>	ROOMS	<i>4</i>	APTS.		SIZE	
------	-------------	---------	----------	-------	----------	-------	--	------	--

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
10/23-42	1 <sup>st</sup> Jump Form OK Winter
11/17-42	2 " Frame OK Winter
12/4/42	3 <sup>rd</sup> / N.S.P. INT + EXT LATH OK R.W. Campbell
1/15/43	4 <sup>th</sup> / N.S.P. Dola: garage completed OK
1/15/43	<p>COMPLETE AND O. K. <i>William W. Campbell</i> INSPECTOR</p>