

R237 F176

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

| | | | |
|---------------------|----------|-----------------------------------|-----------------|
| PERMIT NO. G-196 | LOCATION | 4910 - 8th Avenue | A-1 (29) |
| DATE 4-26-68 | PURPOSE | Repair termite damage to dwelling | |
| | OWNER | F. Martinez | Same |
| ZONE R-1 | ARCH'T | 483-5386 | |
| | CONT'R | Dales Termite Control | 2330-Butano Dr. |

| | | | | | |
|------------|-----------|------------|-----------------|---------------|------|
| VAL. | \$1000.00 | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | 5-7-68 | Rojo | | | |
| SHEET ROCK | | | | | |
| FINAL | 5-10-68 | Rojo | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------|--|
| 5-9-68 | <i>P.T. Frame Flash wall + flashing not right - Chapin</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR