

<b>Lt. 558</b> <b>BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD. \$3.00</b>									
<b>S.L.P.H. #7</b> <b>TYPE BUILDINGS</b> <i>R-76</i> <span style="float: right;"><i>F 296 - 299</i></span>									
<b>PERMIT NO.</b> <b>D-7033</b>	<b>LOCATION</b> <b>1224 - 47th Avenue</b> <b>A-43</b>								
<b>DATE</b> <b>Oct 14 60</b>	<b>PURPOSE</b> <b>Const tool shed in side yard J-1</b>								
<b>ZONE</b>	<b>OWNER</b> <b>Emmons Mc Clung</b>								
<b>ARCH'T</b>	<b>CONT'R</b> <b>Owner GA 8-4372</b>								
<b>VAL. \$ 75.00</b>	<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width: 25%; text-align: center;"><b>STORIES</b></td> <td style="width: 25%; text-align: center;"><b>ROOMS</b></td> <td style="width: 25%; text-align: center;"><b>APTS.</b></td> <td style="width: 25%; text-align: right;"><b>SIZE</b></td> </tr> <tr> <td></td> <td></td> <td></td> <td style="text-align: right;"><b>30 sq. ft.</b></td> </tr> </table>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>				<b>30 sq. ft.</b>
<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>						
			<b>30 sq. ft.</b>						
<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>							
<b>FORM</b>	<i>5-25-61</i>	<i>Fulker</i>							
<b>JOIST</b>									
<b>FRAME</b>	<i>8-25-61</i>	<i>Barbata</i>							
<b>LATH</b>									
<b>FINAL</b>	<i>1-22-62</i>	<i>Cowd</i>							

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
2-3-61	All gates locked. Mt. called. Check plane. Fuller
5-12-61	PT no plans on job. Fuller
8-1-61	Just starting to frame concrete
COMPLETE AND OK	INSPECTOR