

2149-1430-431

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$5.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>		<b>LOCATION</b>				<b>A-1</b>
E-7160		2364 - 39th Street				
<b>DATE</b>		<b>PURPOSE</b>				
May 11-64		Const. addition to detached garage				
<b>OWNER</b>		<b>ARCH'T</b>				
Clarence Mayberry		Same				
<b>ZONE</b>		<b>CONT'R</b>				
R-1		Owner				
		GL 7-3796				
<b>VAL.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>	
\$200.					96 sq.ft.	
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
FORM						
JOIST						
FRAME						
SHEET ROCK						
FINAL	5-27-64	Lansen.				

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS                         |
|------|--|
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      | COMPLETE AND OK <span style="float: right;">INSPECTOR</span> |