

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>3211-A</b>	LOCATION <b>541 - 38<sup>th</sup> St.</b>			
DATE <b>8/26/35</b>	PURPOSE <b>Erect new dwell garage detached</b>			
ZONE	OWNER <b>H. M. Link</b>			
	ARCH'T.			
	CONTR. <b>Jules Johnson - 1923-17<sup>th</sup> St</b>			
VAL. <b>3300<sup>00</sup></b>	STORIES	ROOMS	APTS.	SIZE
		<b>5</b>		<b>76-40</b>
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
9/3. 35	1 <sup>st</sup> Imp. Frame on W.H. Keeter
9/20	2 <sup>nd</sup> " Frame " Keeter
11/1	
11/2	Final Imp. on Keeter
	<p data-bbox="321 823 442 859">COMPLETE AND O. K.</p> <p data-bbox="1092 833 1206 859">INSPECTOR</p>

