

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8350</i>	LOCATION <i>2948 - Stockton Bldg</i>			
DATE <i>5/27/41</i>	PURPOSE <i>Gen. Repairs to front Bldg.</i>			
ZONE <i>-</i>	OWNER <i>Consolidated Ice Co.</i>			
	ARCH'T.			
	CONT'R. <i>Owner</i>			
VAL. <i>760.00</i>	STORIES <i>-</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS	
9/24-4	15' Strip	Forms OK Pinter
10/13-4	2 "	Forms " Pinter

COMPLETE
AND O. K.

INSPECTOR