

Lot 20		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			52.00
Block H		TYPE BUILDINGS			
East Del Paso Heights					
PERMIT NO. F-8730	LOCATION	3925 Marysville Blvd.		A-7	
DATE Oct. 10/67	PURPOSE	Const. warehouse building			
ZONE C-2	OWNER	Howard Colon 3921 Marysville Blvd.			
	ARCH'T	G. S. Porter Sacto.			
	CONT'R	N. M. Alling 3000 Duluth St. W. Sacto.			
VAL.	\$14,500.	STORIES 1	ROOMS	APTS.	SIZE 3,035 sq. ft.
INSP.	DATE	BLDG. TYPE	V no hr.	OCCUPANCY GROUP	PHONE (O) (C)
FORM	11-3-67	Berbats		F-2	371-3135
JOIST					
FRAME	12-8-67	Berbats			
SHEET ROCK	12-12-67	Berbats			
FINAL	2-14-68	Berbats			

ENT

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-20-67	Mc of BB Barb Barbato
11-21-67	12' B.M. call. Unable to make. Reels
1-18-68	Pt Signal - not ready Barbato
1-19-68	Pt Signal - not ready Barbato
	<div data-bbox="291 816 421 871" data-label="Text"> <p>COMPLETE AND OK</p> </div> <div data-bbox="1163 842 1299 868" data-label="Text"> <p>INSPECTOR</p> </div>