

*B144 745*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$10.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b> 4-7336	<b>LOCATION</b> 665 - 54th Street	A-1
<b>DATE.</b> May 27-64	<b>PURPOSE</b> Repair termite damage to dwelling	
<b>ZONE</b> R-1	<b>OWNER</b> C. T. Todd	Same
	<b>ARCH'T</b>	
	<b>CONT'R</b> Paramount Pest Control	6405-Elvas

<b>VAL.</b> \$700.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>Av. SIZE</b>
--------------------	----------------	--------------	--------------	-----------------

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
--------------	-------------	-------------------	------------------------	----------------------

<b>FORM</b>				
-------------	--	--	--	--

<b>JOIST</b>				
--------------	--	--	--	--

<b>FRAME</b>	6-4-64	M. Callaway		
--------------	--------	-------------	--	--

<b>SHEET ROCK</b>	6-12-64	M. Callaway		
-------------------	---------	-------------	--	--

<b>FINAL</b>	6-28-65	P. Kilo		
--------------	---------	---------	--	--

*and termite*

1. within the jurisdiction of the Department of Building Inspection, City of Los Angeles  
 2. within the jurisdiction of the Department of Building Inspection, County of Los Angeles  
 3. within the jurisdiction of the Department of Building Inspection, State of California

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>