

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-24775</i>		LOCATION <i>923-11th street</i>			
DATE <i>3-17-49</i>		PURPOSE <i>Repair fire damage</i>			
ZONE		OWNER <i>Elbie Temple</i>			
		ARCH'T.			
		CONTR. <i>Holden Cont. Co</i>			
VAL <i>\$20,000</i>	STORIES	ROOMS	APTS.	SIZE	
LIGHT SHAFTS			ELEVATOR SHAFTS		
VENT SHAFTS			BOILER ROOMS		
OWNER'S INSPECTOR			SPRINKLER SYSTEM		
LATH			GAS VENTS		
FIRE ESCAPES			CHIMNEYS		
STAND PIPES			SKYLIGHTS		

DATE.	CONDITION OF WORK—REMARKS
3/17/49	Partial Frame Insp. on Fire Damage Repair in No. Section J. E. Bucklin
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>