

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8178</i>	LOCATION <i>2915 2nd St</i>
DATE <i>6/2/31</i>	PURPOSE <i>Repair</i>
ZONE <i>Multiple</i>	OWNER <i>Wm Galluspie</i>
	ARCH'T <i>Owner</i>
	CONT-R <i>Owner</i>

2915 2nd St
PHONES

VAL. <i>170</i>	STORIES	ROOMS	APTS.	SIZE
---------------------------	----------------	--------------	--------------	-------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE

CONDITION OF WORK-REMARKS

6/22/31

Made Partial Insp of the Roofing of Dwy
with Compression Samples H. H. Campbell

COMPLETE
AND O.K.

INSPECTOR