

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-842</i>	LOCATION <i>2917 - GRT.</i>
DATE <i>6/15/38</i>	PURPOSE <i>Repair to roof new downer</i>
ZONE	OWNER <i>W. J. Probst</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="332 973 483 1020">COMPLETE AND O. K.</p> <p data-bbox="1313 992 1475 1020">INSPECTOR</p>