

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS.					INSPECTION AREA		FINAL INSPECTIONS	
		7300 Luther Drive. #196					5-M			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME			1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR.									PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.									CERTIFICATE OF OCCUPANCY	
MECH. CONTR.									ISSUED BY	DATE
ARCH. ENGR.										
OWNER										
CONST. LOAN LENDER										
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
							CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:-

PERMIT NO. S.P. -	MICROFILM RECORD			
ISSUED BY				
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION \$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER	CONTRACTOR & ADDRESS	FINALED BY	DATE
5/27/78	B.F.E. \$ 2800.00	F-2541 \$ 30.00	M/H Set-up	Wilson	Hansen Repair Service 1520 0 St. Lincoln 95628	<i>Shaw 3/28/78 B</i> <i>Shaw 3/28/78 B</i> <i>Shaw 3/28/78 B</i>	
4/21/78	B. \$ 300.00	F-3224 \$ 30.00	8'x40'awning 7'6"x30'deck 12'x44'carport-M/H	Rubin Wilson 196 Amberglen Durajum, Inc. 95826	R.O. Box 26124	<i>Shaw 5/31/78 B</i>	

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
F-2541	R 518 F162				
F-3224	R 521 F286				
F-2341	R 519 F262				
F-3224	R 526 F320				

Shaw