

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-3899</i>	LOCATION <i>1314 - 7<sup>th</sup> Street</i>
DATE <i>2/11/36</i>	PURPOSE <i>Repairs to dwlg. fire loss</i>
ZONE	OWNER <i>W. B. Campbell</i>
	ARCH'T.
	CONT'R. <i>Wm J. J. J. J.</i>

VAL. <i>1000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
2/12/36	2 <sup>ND</sup> INSP. Frame Ya Fire Damage.
	Note, Fireplace on 1 <sup>ST</sup> Floor broken up and 5" Thimble installed for Stone <sup>OK</sup> A. W. Campbell
2/ /36	3 <sup>RD</sup> INSP. INT. WORK Pt. CHIMNEY & CHAS. BELLION.  OK A. W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>