

*R317 F238*

|  |                |  |                     |                             |
|--|----------------|--|---------------------|-----------------------------|
| Lots 697,                                    |                | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD     |                     | \$45.00                     |
| 698, 699, 700, & 701<br>Carleton Subdivision |                | TYPE BUILDINGS   |                     |                             |
| PERMIT NO.<br>H-4713                         |                | LOCATION 2016 - Sutterville Road A-3 (35.01)             |                     |                             |
| DATE<br>Dec. 14-71                           |                | PURPOSE Const. found. for office bldg. move-in           |                     |                             |
| ZONE<br>C-2                                  |                | OWNER Ray D. Henderson P.O. Box 158 Shingle Springs, Ca. |                     |                             |
|  |                | ARCH'T W. J. Alexander                                   |                     |                             |
|  |                | CONTR H. F. Konvalin 2424 - Walnut Avenue                |                     |                             |
| VAL. \$8,500.                                |                | STORIES<br>1   | ROOMS               | APTS. SIZE<br>2,834 sq. ft. |
| INSP.  | DATE           | BLDG. TYPE V No Hr                                       | OCCUPANCY GROUP F-2 | PHONE (O) (C)<br>489 2742   |
| FORM   | <i>1-18-72</i> | <i>Submits 2-1-72 Submits</i>                            |                     |                             |
| JOIST  |                |  |                     |                             |
| FRAME  |                | <i>Submits</i>   |                     |                             |
| SHEET ROCK                                   |                | <i>Submits</i>   |                     |                             |
| FINAL  | <i>4-25-72</i> | <i>Submits</i>   |                     |                             |

*R317 F244-247 plus*

| DATE               | SPECIAL CONDITIONS OF WORK — REMARKS   |
|--------------------|--|
| 1-16-72            | ok slab <span style="float: right;">Substrate</span>                             |
| 2-8-72             | ok shear walls <span style="float: right;">Substrate</span>                      |
| 3-27-72            | Materials - Left note to call. Unfilled<br>No required, or glass doors Substrate |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
| COMPLETE<br>AND OK | INSPECTOR  |