

R-63

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD # 145-

TYPE BUILDINGS \$6.00

PERMIT NO. D-4070	LOCATION 4409 - 54th St. A-1
DATE Nov. 19, 59	PURPOSE Repair termite & rot Damage dwelling
ZONE	OWNER Estate of Bertha Fenske
	ARCH'T
	CONT'R Orchard Supply Co. 1731 17th St. HI 6-7821

VAL.	\$550.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR			
FORM					
JOIST					
FRAME					
LATH					
FINAL					

1959 Edition of Building Inspector's Report Card, Form No. 1, published by the Department of Public Works, City and County of Honolulu, Hawaii.

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	COMPLETE AND OK
	INSPECTOR