

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No chg</i>	LOCATION <i>1225-30th St.</i>
DATE <i>10/25/31</i>	PURPOSE <i>Repair</i>
OWNER <i>M. Larch</i>	PHONES
ZONE <i>Jan</i>	ARCH'T
	CONT-R <i>Ormond</i>

VAL. <i>Under 100</i>	STORIES	ROOMS	APTS.	SIZE
--------------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
10/29/31	Partial Drop of Re Roofing of Dwg with Cedar Shingles over old roof.
	13 1/2 M. Shingles A. M. Campbell
	COMPLETE AND O.K.
	INSPECTOR