

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>9772</i>	LOCATION <i>2575 D St</i>			
DATE <i>7/29/32</i>	PURPOSE <i>Remod</i>	PHONES		
ZONE <i>Multifamily</i>	OWNER <i>Wes Wakefield</i>			
	ARCH'T <i>Wes Wakefield</i>			
	CONT-R <i>Wes Wakefield</i>			
VAL. <i>200-</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK--REMARKS
8/3/32	Partial Insp. Carpenter now reshingling
	Roof of Dwlg. O.R. A.H. Campbell
8/10/32	Re Shingling; completed O.R. A.H. Campbell
8/10/32	COMPLETE AND O. K. <i>A.H. Campbell</i> INSPECTOR