

R 22 / 339-342

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$60.00

TYPE BUILDINGS

006-101-20

| | | | |
|------------|-------------------------|---|--|
| PERMIT NO. | H-5426 | | |
| LOCATION | 911 - K Street A-2 (10) | | |
| DATE | PURPOSE | Feb. 8-72 Install sprinkler system in hotel bldg. | |
| ZONE | OWNER | Harry Redler 611 - K Street | |
| | ARCH'T | | |
| | CONT'R | Central Pacific Spr. Co. 1100-65th St. | |

| | | | | | | | | | |
|------------|-----------|---------------|-----------------|-------|---|-------|---------------|----------|--|
| VAL. | \$14,000. | STORIES | 5 | ROOMS | | APTS. | | SIZE | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | | H | | PHONE (O) (C) | 452 0224 | |
| FORM | | | | | | | | | |
| JOIST | | | | | | | | | |
| FRAME | | | | | | | | | |
| SHEET ROCK | | | | | | | | | |
| FINAL | 4-20-72 | <i>Chapin</i> | | | | | | | |

1972-73 State Building Code, Chapter 16, Section 16.01, Building Inspection Report Card

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |