

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-9765</i>	LOCATION <i>2011 - J St.</i>			
DATE <i>12/29/41</i>	PURPOSE <i>Erect paint shop - auto shop</i>			
ZONE <i>L</i>	OWNER <i>Farrell & Fris.</i>			
	ARCH'T. <i>Wm H. Miller</i>			
	CONTR. <i>Wm H. Miller</i>			
VAL. <i>4000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
12/29/41	1 ST /NSP. Forms in place ^{OK} A.W. Campbell
2/3/42	2 ND /NSP. Frame . . . ^{OK} A.W. Campbell
2/11/42	3 RD /NSP. Ext. Lath ^{OK} A.W. Campbell
	Note. On account of inability of Contractor to
	procure Galv. Iron for Front & Rear Walls, he
	changed to Rock Lath & Plaster noted ^{OK}
	Inspected Approach on J. St. ^{A.W. Campbell} A.W. Campbell
2/25/42	4 TH /NSP. Band & Rebar Workhouse Completed
2/25/42	COMPLETE AND O. K. <i>Arthur W. Campbell</i>
	INSPECTOR