

*AP 157 7450 - 434*

|                       |                |  |                 |                                  |               |
|-----------------------|----------------|--|-----------------|----------------------------------|---------------|
| Lot 221               |                | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD |                 |                                  | \$46.00       |
| <b>TYPE BUILDINGS</b> |                |  |                 |                                  |               |
| South Oak Park        |                |  |                 |                                  |               |
| PERMIT NO.            |                |  |                 |                                  |               |
| E-9110                |                | LOCATION   |                 | 3724 - 7th Avenue A-1            |               |
| DATE                  |                | PURPOSE  |                 |                                  |               |
| Dec. 3-64             |                | Const. dwelling & attached gar.                      |                 |                                  |               |
| ZONE                  |                | OWNER  |                 | Bill Davis 4218-Fell St. Oakland |               |
| R-1                   |                | ARCH'T   |                 | 457-5948                         |               |
|                       |                | CONT'R   |                 | Hosie Huston 5920-Wallace Avenue |               |
| VAL. \$12,100.        |                | STORIES  | ROOMS           | APTS.                            | 286-gar. SIZE |
|                       |                | 1  |                 |                                  | 1,296 sq.ft.  |
| INSP.                 | DATE           | BLDG. TYPE   | OCCUPANCY GROUP | PHONE (O) (C)                    |               |
| FORM                  | <i>12/7/64</i> | <i>Perls</i>   |                 |                                  |               |
| JOIST                 | <i>2-8-65</i>  | <i>Perls</i>   |                 |                                  |               |
| FRAME                 | <i>2-14-65</i> | <i>Perls</i>   |                 |                                  |               |
| SHEET ROCK            | <i>2-18-65</i> | <i>Perls</i>   |                 |                                  |               |
| FINAL                 | <i>2-18-65</i> | <i>Perls</i>   |                 |                                  |               |

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

| DATE    | SPECIAL CONDITIONS OF WORK — REMARKS  |
|---------|---|
| 3-18-65 | PT. frame (Hatch 2x5 ceiling joint)   |
|         | (Kitchen vent) (Cont.)  |
| 6-14-65 | P. 1. Fire wall in garage + in water heater rm.<br>2. address chug. (3) front side walls (4) front<br>steps - risen to the same |
| 8-10-65 | P. 1. (corrections) not made Back to<br>Cooper  |
|         |   |
|         |   |
|         |   |
|         |   |
|         |   |
|         | COMPLETE<br>AND OK  |

INSPECTOR