

R-152 F521

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO. E-8336		LOCATION 501 - 15th Street A-2			
DATE Sep 11-64		PURPOSE Repair damage to front porch			
ZONE		OWNER Natividad Valdivia Same			
		ARCH'T GI 2-5624			
		CONTR Chas. Vanina 2022-Capitol Ave.			
VAL.	\$400.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>P. Blalock</i>				

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK INSPECTOR