

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>63-12486</i>		LOCATION <i>316-16th St.</i>		
DATE <i>7/12/44</i>		PURPOSE <i>Repairs to Bldg. fire loss</i>		
ZONE <i>—</i>		OWNER <i>Owner</i>		
		ARCH'T.		
		CONTR. <i>Owner</i>		
VAL. <i>1000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
7/31/44	<p>2ND Insp. Frame for General Repairs to Bldg recently damaged by Fire. ^{OK} M.W. Campbell</p> <p>3RD Insp. 1/2" Sheet-Rock for Walls + Ceiling of upper story in rear of Bldg</p>
COMPLETE AND O. K.	INSPECTOR