

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10627</i>	LOCATION <i>1905 - 1st</i>
DATE <i>8-19-42</i>	PURPOSE <i>Reshingle with wood Shingles.</i>
ZONE	OWNER <i>Bessie Arnold</i>
	ARCH'T.
	CONTR. <i>Bingham Const Co</i>
VAL. <i>160⁰⁰</i>	STORIES
	ROOMS
	APTS.
	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
9/15/42	Restructuring of Row 172 Shanty Complete
9/15/42	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. <i>Walter H. Campbell</i> INSPECTOR </div>