

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-4338</i>	LOCATION <i>714 - 11th Street</i>
DATE <i>11/27/39</i>	PURPOSE <i>Re-face exterior walls</i>
ZONE <i>Gen. Com.</i>	OWNER <i>H. Bianchi, Plumber</i>
	ARCH'T.
	CONTR. <i>Yepco Woon</i>

VAL. <i>17500</i>	STORIES <i>3</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
11/30/39	<p>3<sup>rd</sup> / NSP - EXT LATN 18-gauge chlorine wire applied over old Paper on old plaster on East Side of 3<sup>rd</sup> Street Rooming House</p> <p>Same nailed with approved furring nails. Furring, the wire out 1/2" from wall.</p> <p style="text-align: center;">N.W. Campbell</p>
	<p>COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span></p>