

*R213F-352*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$6.00**

**TYPE BUILDINGS**

PERMIT NO. <b>H-3907</b>		LOCATION <b>6333 - 9th Avenue A-1 (29)</b>			
DATE <b>Oct-19-71</b>		PURPOSE <b>Reroof dwelling</b>			
ZONE		OWNER <b>Paul Shelton</b>		Same	
		ARCH'T		<b>371-6876</b>	
		CONT'R <b>Jack Snyder P.O. Bx. 693 W. Sacto.</b>			
VAL. <b>\$100.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>4-23-72</i>	<i>Dana Fuller</i>			

10-11-1954

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>