

R-317F142-193600

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$12.00

TYPE BUILDINGS

| | | | | | |
|-------------|----------|------------------------------------|-------|------------------------|------------------|
| PERMIT NO. | | | | | |
| H-4647 | | LOCATION | | 1517 - 24th Street A-2 | |
| DATE | | PURPOSE | | | |
| Dec. 13-71 | | Const. carport to rear of dwelling | | | |
| | | OWNER | | Jack Fernandez Same | |
| ZONE | | ARCH'T | | | |
| R-1 | | CONTR | | | |
| | | Orval A. Sweeden 4758 - Robin Ct. | | | |
| VAL. \$700. | | STORIES | ROOMS | APTS. | Rocklin, Ca SIZE |
| | | | | | 292 sq. ft. |
| INSP. | DATE | BLDG. TYPE | | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 12-14-71 | <i>Single</i> | | | 624 2684 |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| FINAL | 3-6-73 | <i>M. Callaway</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 2-15-72 | L. J. Smith - H. J. Smith Gours |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |