


2184 7513

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>		<b>LOCATION</b>		<b>APT.</b>	
R-2767		535 - 38th Street		A-1	
<b>DATE</b>		<b>PURPOSE</b>		<b>OWNER</b>	
Jan 11-66		Repair termite damage to dwelling		Mrs. L. Mills same	
<b>ZONE</b>		<b>ARCH'T</b>		<b>CON'TR</b>	
R-1		Valley Termite		1617-18th St. 448-1887	
<b>VAL.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
\$300.					
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME SHEET ROCK</b>	1-13-66	Masonry			
<b>FINAL</b>	1-18-66	Rico			ent



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b>
	<b>INSPECTOR</b>

