

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-19303	LOCATION 2527 - T St.
DATE 4/27/42	PURPOSE Repairs to dwg.
ZONE	OWNER P. Mikasich, J.
	ARCH'T.
	CONTR. Owner

VAL. 180	STORIES <u> </u>	ROOMS <u> </u>	APTS.	SIZE
---------------------	------------------------	----------------------	-------	------

LIGHT SHAFTS	350⁰⁰	ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/6/22	2 nd / 10 th Floor for Alterations & Repairs.
	to interior of Dwyer ^{OK} A.W. Campbell
	Note Raised Valuation with Owner's consent
	to include rebuilding of Parade Mantel
	lowered from wall. from 185 ⁰⁰ to 350 ⁰⁰
	A.W. Campbell
	<p data-bbox="302 880 438 927">COMPLETE AND O. K.</p> <p data-bbox="1179 906 1323 932">INSPECTOR</p>