

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

|                              |         |  |       |
|------------------------------|---------|--|-------|
| PERMIT NO.<br><i>B-24335</i> |         | LOCATION<br><i>1547 - 34<sup>th</sup> Street</i>   |       |
| DATE<br><i>1/27/49</i>       |         | PURPOSE<br><i>Repair to understructure termite</i> |       |
| ZONE                         |         | OWNER<br><i>M. Alameda</i>                         |       |
|                              |         | ARCH'T.  |       |
|                              |         | CONTR.<br><i>Richard Ruggely Co.</i>               |       |
| VAL. <i>368<sup>00</sup></i> | STORIES | ROOMS  | APTS. |
|                              |         |  | SIZE  |
| LIGHT SHAFTS                 |         | ELEVATOR SHAFTS                                    |       |
| VENT SHAFTS                  |         | BOILER ROOMS                                       |       |
| OWNER'S INSPECTOR            |         | SPRINKLER SYSTEM                                   |       |
| LATH                         |         | GAS VENTS  |       |
| FIRE ESCAPES                 |         | CHIMNEYS   |       |
| STAND PIPES                  |         | SKYLIGHTS  |       |

| DATE   | CONDITION OF WORK-REMARKS    |
|--------|------------------------------|
| 3/3/49 | Final Insp. H. Jones         |
|        |                              |
|        |                              |
|        |                              |
|        |                              |
|        |                              |
|        |                              |
|        |                              |
|        | COMPLETE AND O. K. INSPECTOR |