

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No charge</i>	LOCATION <i>709-10th St</i>			
DATE <i>Apr. 2nd 1935</i>	PURPOSE <i>Make Repairs to Front Porch & Steps</i> PHONES			
ZONE <i>Gen</i>	OWNER <i>P. H. SULLIVAN. 600 L. St.</i>			
	ARCH'T			
	CONT'R <i>Owner. (day-work)</i>			
VAL. <i>50⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
4/2/35	<p>Made Partial Snap. in Pabain's to Front Porch. Notified Owner to get the Permit and to install 4 brick or concrete Piers for support of 4 Columns of Porch. Proj. No. 100/100/100</p>
COMPLETE AND O. K.	INSPECTOR