1500 - 7th Street A-2

1500-7th st

## RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE | |
|---|---|---|---|---|---|---|---|---|
| 7/8/65 | B. $20,000. | F-1083 $67. | Const. Elevator shaft on North side of pkng. gar | Capitol Mall Tract | Commercial Consts. 4341 Lamont Way | Court | 1/19/66 | |
| 1/25/66 | M. $4,000. | F-2916 $19. | Inst. ventilation system for restaurant | Harry Barrick & Michael Barton | Owner Cancelled 1st Cancelled 8-29-66 | Fuller | 9/13/66 | |
| 4/15/66 | B. $500. | F-3848 $5.00 | Const. partition in office | Capitol Towers | Patterson Travel Agency 1500-7th St. | Calloway | 5/16/66 | |
| 3/26/75 | E. $150. | C-1976 $7.50 F-6779 | Replace elect. panel Apt. | Capitol Towers 631 N Street | Owner | McDowell | 9/29/75 | |
| 9/17/75 | B.P.E. $1,500. | C-7472 $20. | Inst light fixture, indirect waste pipe existing - Comm. | Stephen Duckels | Owner | Barbato<br>White<br>Reynoso | 9-26-75<br>1-5-76<br>4-8-76 | B<br>E&P |
| 1/9/76 | M.E.M. $16,165. | D-0148 $130. G6752 | A/C fan cool units & roof condensers, Elect. connection for service | Capitol Towers Trust Same | #2 Park Sheet Metal 5061 - 24th Street | Collins<br>Cracchiolo | 5-19-76<br>10/7/76 | M<br>E |
| 9/12/74 | P. $100. | B-6995 $7.50 | Gas Test - Apt. #663 | Capitol Towers | Owner | Reynoso | 9/13/74 | |
| 1/21/76 | P. $850. | D-366 $15. | Inst. grease interceptor | Terry Mulligan | Owner | Reynoso | 4-8-76 | |
| 3/3/76 | M.E. $32,610. | D-1422 $222. G6802 | Inst. Htg & A/C-Apts. | Capitol Towers 1500 - 7th Street | Park Sheet Metal 5061-24th Street | Collins<br>Bellissen | 5-19-76<br>10/19/76 | M<br>E |
| 4-29-76 | B-P-E $5,000. | D- 2988 $46. | Install heated pool spa at apt. bldg. | Capitol Towers same | Calif. Poolman INC. 5378-Sunrise Blvd. F.O. | Reynoso<br>Barbato<br>Sullivan | 12/27/76<br>1/27/77<br>3/21/77 | P<br>B<br>E |
| 5-14-76 | M.E.$6,875. | D-3471 $60 G6078 | Install A/C | Capitol Towers | Park Sheet Metal 5061 24th St | Jacoby<br>Cracchiolo | 6-30-76<br>8/4/76 | E |
| 5-19-76 | Bldg. $500. | D-3641 $10. | Platform for A/C in restaruant bldg. | Capitol Tower same | A-1 Const. Co. 5608-Rickey Dr. | Barbato | 6-10-76 | |
| 3/20/78 | B.P.E.M$ 1000.00 | F-2150 $ 30.00 H-0181 | Interior work plumbn & elct for Pastry Shop | Wilson & Loronzo 694 N St. | Owner Same 95814 | Kaetting<br>Barbato<br>Helmrich | 5/5/78<br>5/5/78<br>5/1/78 | E<br>B<br>EM |

## MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|---|---|---|---|---|---|
| F-1083 | R 172 F 491 - 497 | D-0148 | R433F314 | D-3471 | R414 F 191 |
| F-1083 | R 185 F 344 File | F3648 | R433F314 | D-3641 | R-414 F-364 |
| F-1083 | R 187 F 593 Report | F1083 | R433F314-315 Combined | D-364 | R476F324 final |
| F-2916 | R 185 F 441 - 444 | F2916 | R433F314-315 Combined | D-2988 | R476F479 |
| F-3848 | R 192 F 47 | B-6995 | R 394 F 100 | D-366 | R476F327 final |
| C-1976 | R 409 F 131 | B-6995 | R 394 F 397 Final | D-3471 | R476F328 final |
| C-1976 | Final | D-366 | R 434 F 115 | D-0148 | R476F325 final |
| C-7472 | R 425 F 369 | | | D-1422 | R476F327 final |
| C-7472 | R476F326 final | D-1422 | R433F005 | D-2988 | R476F323-324 finaled |
| F-2150 | R516F600-601 | D-2988 | R433F502 | C-1976 | R476F325 final |
| | | | | F 2150 | R550F036 final |

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.

JOB ADDRESS: 1500 - 7th Street

INSPECTION AREA: 2

LEGAL DESCRIPTION: Ptn. of Block N to P, 5th & 7th Streets

| OCCUP. GR. | CONST TYPE | VAR. NO. | FIRE ZONE |
|---|---|---|---|
| F-3 | | | |

| TITLE AND NAME | | I/C | ADDRESS | ZIP | CITY LIC. NO. | TEL. NO. |
|---|---|---|---|---|---|---|
| GEN. CONTR. | Capitol Mall Tract | | 111-519 Forum Bldg. | | | |
| ELEC. CONTR. | | | | | | |
| PLBG. CONTR. | | | | | | |
| MECH. CONTR. | | | | | | |
| ARCH. ENGR. | Wurster, Bernardi, Emmons | | S. F., CA | | | |
| OWNER | Capitol Mall Tract | | 111-519 Forum Bldg. | | | |
| CONST. LOAN LENDER | | | | | | |

| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOF CONSTR. | AREA 1st FLOOR | TOTAL AREA | C.S.D. | C.I. CASE |
|---|---|---|---|---|---|---|---|---|
| | | | 3 | | | 16,320 | CENSUS TRCT. NO. | |

| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | TREES RMVD. | EXISTING BLDG'S SAME LOT | HOW USED |
|---|---|---|---|---|---|---|---|---|
| | | | R-5 | | | | | |

NATURE OF WORK:- Const. Parking gar for Capitol Mall MI 7-9700 Rooms

| | |
|---|---|
| PERMIT NO. S.P. | E-3179 |
| ISSUED BY | |
| ISSUANCE DATE | 2/6/63 |
| VALUATION | $ 242,000 |
| R.D.F. FEE | $ |
| S.M.I. FEE | $ |
| PLAN CK. FEE | $ |
| SEWER INCL. FEE | $ |
| PERMIT FEE | $ 361.50 |
| | $ |
| | $ |
| TOTAL FEES | $ 361.50 |

MICROFILM RECORD

| | | | |
|---|---|---|---|
| ~~PLANS AND~~ APPLICATION | REEL NO. 115 | FRAME NO:- 14 | TO 345 |
| INSPECTION RECORD | ~~REEL NO.~~ R033F316 | ~~FRAME NO.~~ 317 Combine | |
| JOB FILE | REEL NO. | FRAME NO:- | TO |
| REV. | 115 | 346 | |
| R | 165 | 323 File | |

REMARKS AND/OR VARIANCES

FINAL INSPECTIONS

| BUILDING BY | DATE |
|---|---|
| E. Larsen | 2/17/65 |
| ELECTRICAL BY | DATE |
| PLUMBING BY | DATE |
| MECHANICAL BY | DATE |

CERTIFICATE OF OCCUPANCY

| ISSUED BY | DATE |
|---|---|
| | |

BI-FI-R