

*R236F22*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

PERMIT NO. <b>G-29</b>		LOCATION <b>4026b - 38th Street A-3 (37)</b>			
DATE <b>4/8/68</b>		PURPOSE <b>Repair fire damage to detached garage.</b>			
ZONE <b>R-1</b>		OWNER <b>Jessie Brinkley 3501 - 16th Ave.</b>			
		ARCH'T <b>IV3-9246</b>			
		CONT'R <b>Bldg. &amp; Improv. Co. 2530 Tisela Way</b>			
VAL. <b>\$300.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM					
JOIST					
FRAME SHEET ROCK	<i>4/10/68 McCalloway</i>				
FINAL	<i>4/10/68 McCalloway</i>				

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>