

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. 6516	LOCATION <i>Lot 3 Block D Fairview. 3723 47th St.</i>		
DATE <i>July 1 1930</i>	PURPOSE <i>Remodel Interior and Make New Rep to Complete 6 Room Ft. Stucco</i>	ROOMS	APTS.
ZONE <i>2-Family District</i>	OWNER GABRIEL O'RELLI	PHONE <i>Dirty, partially constructed on lot.</i>	
	ARCHT	CONTR OWNER	
	VAL. <i>1000⁰⁰</i>	STORIES <i>1</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys	Cement Tests
Ex Wall	Joints							
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
7/13-30	1 Imp Forms in place on P.H. Printer
8/5-30	2 Imp Frame in place on P.H. Printer
10/27-30	3 " Int Ext Lock on P.H. Printer
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: right;">INSPECTOR:</p>

