

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>No ch</i>	LOCATION <i>2330-14<sup>th</sup> St.</i>
DATE <i>10-4-32</i>	PURPOSE <i>Re-roofing Composition Shingles</i>
ZONE	OWNER <i>Phyllis White</i>
	ARCH'T
	CONT-R <i>Chas. D. Guerson</i>
	PHONES <i>9491-Beinn</i>

VAL.

*73 00*

STORIES

ROOMS

APTS.

SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="319 847 467 895"><b>COMPLETE AND O. K.</b></p> <p data-bbox="1072 874 1226 895"><b>INSPECTOR</b></p>