

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4103</i>	LOCATION <i>729 - R St -</i>
DATE <i>8/31/36</i>	PURPOSE <i>Elec. Repair</i>
ZONE	OWNER <i>Jessen, L. Halberg</i>
	ARCH'T.
	CON'T.R. <i>Stirling Elec - 907 - 8 St</i>

VAL. <i>200 u</i>	STORIES	ROOMS	APTS.	SIZE <i>9'-0" x 6'-5"</i>
-------------------	---------	-------	-------	------------------------------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
4/13/36	Made inspection of the Kennel Club
	Linn Park near the 16th St. bridge
	The main enclosure is 36 ft. in
	perimeter of concrete, topped with
	and topped with 12 ft. of chain link
	fencing.
4/13/36	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>