

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>9568</b>	LOCATION <b>2nd Floor</b>	1212-19 <sup>th</sup>	
DATE <b>6/3/32</b>	PURPOSE <b>Paint Br Auto Repair Shop</b>	PHONES	
ZONE <b>Gen Com</b>	OWNER <b>Angelo Basso</b>		
	ARCHT <b>W. L. J. S.</b>		
	CONT-R <b>J. O. Johnson</b>		
VAL. <b>2nd -</b>	STORIES <b>2</b>	ROOMS	APTS.
			SIZE <b>60X46</b>
Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
6/13/32	1 <sup>ST</sup> / ASP. Footings for 1-Story Public Garage. Contractor enlarged the 6 plastic pipes to 3'-4" long by 2 feet wide to 18" dia. <sup>at</sup> M. Campbell
6/17/32	2 <sup>ND</sup> / ASP. (PARTIAL) Brick walls up. <sup>for building 16' x 16'</sup> Brick tiers on alley side. M. Campbell
8/4/32	4 <sup>TH</sup> / ASP. 1-Story Brick Store Bldg Completed.
8/4/32	ISSUED CERTIFICATE OF OCCUPANCY #9568
8/4/32	Street Cleaned up OR M. Campbell
8/4/32	COMPLETE AND O. K. <i>Allen H. Campbell</i> INSPECTOR